
Perry Memorial Conservation Area Range Complex Renovation, Recycling, and Soil Stabilization

Highway 23 Range – Site Characterization




Site Locations

Highway 23 Range






Hwy 23 Range Layout













Bullet Migration

- Backstop Wear/Erosion
 - Changes Shape
 - Dishes Face
 - Concentrates Bullets







Bullet Migration

- Tumbling
 - May Reduce Particle Size

Shooting Position








Characterization Design

- Reconnaissance

- Range Floor

- Backstops

- Overshot/Drainage






Sampling Locations

- Over 100 samples

- Lead
- Arsenic
- Antimony
- Copper
- Zinc





Zoom to show Additional Characterization **Sample Locations**

- **Range Floor**
 - Pads + 15 ft
 - **Midpoints**
 - **Target Holders**
 - **Drainage Ways**
- **Backstops**
 - Face
 - Apron
 - Core
- **Overshot Area**
 - Grid
 - **Refinement Pts**
 - Recon. Pts





Sampling Protocol

- Clayey Soils
- Avoid "Smear"
 - Oversized Holes
 - Scrape Sidewalls
 - "Core" Horizontally
- Avoid Carryover
 - Tool Cleaning
 - Equipment Blanks
























Soils Recommended for Beneficial Reuse

- Backstop Improvements at New Range

 New Range has Extensive Berms

PARKING LOT

- (This Graphic Only Shows Sub-Grade soils)






Reuse Soils Recommended for Treatment

- Reduction of Leachability


- (This Graphic Only Shows Sub-Grade soils)





Reuse Plan

- Process for Metal Recycling
 - Green area
 - Yellow areas
 - Red areas
- Soil Treatment
 - Yellow areas
 - Red areas
- Backstop Improvements
 - Yellow areas
 - Red Areas






Additional Reconnaissance

- Bullet-Struck Trees


- Possibly Contain Lead













Ken Ewers, R.G.
Project Manager, Environmental Geologist **GREDELL** Engineering Resources, Inc.
573-659-9078

kene@ger-inc.biz www.ger-inc.biz

